

Theory and Practice of strain gages

單秋成

Related Sections in the Textbook

E. O. Doebelin, Measurement Systems:- Application and design, 5th ed., McGraw Hill, 2003

- ✓ Sec.4.3 pp. 228-253
- ✓ Chap.5 pp. 432-480
- ✓ Sec.10.1 pp.837-843

單秋成

Introduction to resistance strain gage

- Equipment for strain measurement.
- Basic theory of resistance strain gage
- Fundamental structure of strain gages
- How to Install a strain gage
- The Wheatstone bridge
- Factors that affect the accuracy of strain gages
- How to select a suitable strain gage

單秋成

The Wheatstone bridge

- The Wheatstone bridge
- Interrogation of the Wheatstone bridge
- Balancing the bridge
- Calibration of the bridge
- Temperature compensation techniques
- Strain gage layout for different applications

單秋成

General sensor characteristics

- ◆ **Sensors:**
Convert a Signal or Stimulus (Representing a Physical Property) into an Electrical Output
- ◆ **Transducers:**
Convert One Type of Energy into Another
- ◆ The Terms are often Interchanged
- ◆ **Active Sensors Require an External Source of Excitation:**
RTDs, Strain-Gages
- ◆ **Passive (Self-Generating) Sensors do not:**
Thermocouples, Photodiodes

www.analog.com/library/analogDialogue/archives/39-05/Web_Ch4_final.pdf

單秋成

Typical sensors and their output formats

PROPERTY	SENSOR	ACTIVE/ PASSIVE	OUTPUT
Temperature	Thermocouple	Passive	Voltage
	Silicon	Active	Voltage/Current
	RTD	Active	Resistance
	Thermistor	Active	Resistance
Force / Pressure	Strain Gage	Active	Resistance
	Piezoelectric	Passive	Voltage
Acceleration	Accelerometer	Active	Capacitance
Position	LVDT	Active	AC Voltage
Light Intensity	Photodiode	Passive	Current

www.analog.com/library/analogDialogue/archives/39-05/Web_Ch4_final.pdf


單秋成

Gages for measuring strain

單秋成

Mechanical strain gage

- A mechanical dial gage.



http://measure.feld.cvut.cz/groups/edu/e38sz/Lectures/04-mechanical_strain.pdf

單秋成

Acoustical strain gage

- resonant frequency f_o of string with length l and mass m depends on stretching force F

$$f_o = \frac{1}{2} \sqrt{\frac{F}{ml}}$$

$$\rho = \frac{m}{V} = \frac{m}{lS}$$


$$\sigma = \frac{F}{S} = \epsilon E$$

$$\frac{\Delta l}{l} = \epsilon \dots \text{relative deformation}$$

$E \dots$ Young module of elasticity
 $\sigma \dots$ mechanical stress



$$f_o = \frac{1}{2l} \sqrt{\frac{\sigma}{\rho}} = \frac{1}{2l} \sqrt{\frac{\epsilon E}{\rho}}$$








http://measure.feld.cvut.cz/groups/edu/e38sz/Lectures/04-mechanical_strain.pdf

單秋成

Some resistance displacement/strain sensors

Potentiometric Sensors



Resistive (conductive) element
• wire-wound
• cermet
• conductive plastic


<http://www.me.utexas.edu/~lotario/me244L/lecs/sensors/rsensors.pdf>

單秋成

Resistance Strain gage

單秋成

What is a resistance strain gage?



<http://www.kyowa-ei.co.jp/english/images/whats.pdf>

單秋成

Pizeoresistive effect


- Lord Kelvin showed in 1856 that the resistance of copper and iron wires changed when they are subjected to mechanical strain.
- The change in resistance is very small and cannot accurately be measured by an digital ohmmeter on a DVM.
- In the absence of any electronic amplifier, Lord Kelvin used a null detection method to measure the resistance changes.

單秋成

Principle of Piezoresistive effect

- basic relation:

$$R = \frac{1}{S} \rho$$




http://measure.feld.cvut.cz/groups/edu/e38sz/Lectures/04-mechanical_strain.pdf

單秋成

Sensitivity of a strain gage


Gage factor (GF)



<http://www.kyowa-ei.co.jp/english/images/whats.pdf>

單秋成

Gage factors of some metals



<http://www.ae.gatech.edu/people/jcraig/ae3145/Lab2/strain-gages.pdf>

單秋成

Gage factors of some metals

Table 1. Gage Factors for Various Grid Materials

Material	Gage Factor (GF)		Ultimate Elongation (%)
	Low Strain	High Strain	
Copper	2.6	2.2	0.5
Constantan*	2.1	1.9	1.0
Nickel	-12	2.7	--
Platinum	6.1	2.4	0.4
Silver	2.9	2.4	0.8
40% gold/palladium	0.9	1.9	0.8
Semiconductor**	~100	~600	--

* similar to "Ferry" and "Advance" and "Copel" alloys.

** semiconductor gage factors depend highly on the level and kind of doping used.


<http://www.ae.gatech.edu/people/jcraig/ae3145/Lab2/strain-gages.pdf>

單秋成

Gage factors of some metals

Example 1

Assume a gage with $GF = 2.0$ and resistance 120 Ohms. It is subjected to a strain of 5 microstrain (equivalent to about 50 psi in aluminum). Then



Example 2

Now assume the same gage is subjected to 5000 microstrain or about 50,000 psi in aluminum:



<http://www.ae.gatech.edu/people/jcraig/ae3145/Lab2/strain-gages.pdf>


單秋成

Introduction to resistance strain gage

- Equipment for strain measurement.
- Basic theory of resistance strain gage
- Fundamental structure of strain gages
- How to Install a strain gage
- The Wheatstone bridge
- Factors that affect the accuracy of strain gages
- How to select a suitable strain gage

單秋成

Different types of piezoresistive strain gage



http://measure.feld.cvut.cz/groups/edu/e38sz/Lectures/04-mechanical_strain.pdf

單秋成

PARAMETER	METAL STRAIN GAGE	SEMICONDUCTOR STRAIN GAGE
Measurement Range	0.1 to 40,000 $\mu\epsilon$	0.001 to 3000 $\mu\epsilon$
Gage Factor	2.0 to 4.5	50 to 200
Resistance, Ω	120, 350, 600, ..., 5000	1000 to 5000
Resistance Tolerance	0.1% to 0.2%	1% to 2%
Size, mm	0.4 to 150 Standard: 3 to 6	1 to 5

Figure 4-26: A comparison of metal and semiconductor type strain gages

www. analog.com/library/analogDialogue/archives/39-05/Web_Ch4_final.pdf 單秋成

Transverse sensitivity


A single section of wire along a small gage length is not sensitive enough. Must have a number of sections looped together.

Transverse strain affects the resistance of the strain gage:

- ✓ through poisson ratio effect, on the axial portion of the gage.
- ✓ On the transverse portion of the gage.

單秋成

The metal foil strain gage




- ◆ PHOTO ETCHING TECHNIQUE
- ◆ LARGE AREA
- ◆ STABLE OVER TEMPERATURE
- ◆ THIN CROSS SECTION
- ◆ GOOD HEAT DISSIPATION

www.analog.com/library/analogDialogue/archives/39-05/Web_Ch4_final.pdf

單秋成

Structure of a foil strain gage



<http://www.kyowa-ei.co.jp/english/images/whats.pdf>

單秋成

Introduction to resistance strain gage

- Equipment for strain measurement.
- Basic theory of resistance strain gage
- Fundamental structure of strain gages
- How to Install a strain gage
- The Wheatstone bridge
- Factors that affect the accuracy of strain gages
- How to select a suitable strain gage

單秋成


How to install a gage

B129

單秋成

Surface preparation

- Brushing off loose particles
- Remove paint, rust and plating
- degreasing
- Abrading for optimum bonding



http://www.vishay.com/brands/measurements_group/guide/ta/csc/csc.htm



Class of installation	Surface Finish, rms microinch	Surface Finish, rms micrometer
General stress analysis	63 - 125	1.6 - 3.2
High elongation	>250*	>6.4*
Transducers	16 - 63	0.4 - 1.6
Ceramic cement	>250	>6.4

http://www.vishay.com/brands/measurements_group/guide/ib/b129/129c1.htm

單秋成


Surface preparation

- For transducer application where good and long lived bonding is needed, etching with dilute acid may be applied followed by neutralizing with an alkali.
- Mark off the layout lines for the strain gage position using light scribing or burnishing with a 4H drafting pencil .

單秋成

Surface preparation

- Re-clean the gage position thoroughly with degreaser (move in one direction with force) , neutralize if necessary.



<http://www.kyowa-ei.co.jp/english/images/whats.pdf>

單秋成

Handling of the strain gages


- Never touch strain gages by hand
- Handled only with rounded tweezers, or vacuum pen.
- Hold strain gage at the backing support, not at sensor grid.
- Strain gages do not require cleaning before bonding unless they have been accidentally contaminated by the user.
- Should strain gages have been touched by hand, clean it immediately with IPA and cotton tipped applicators, (do not use cotton applicators with plastic grip).

<http://www.blh.de/application/appl145b.htm>

單秋成

Gage bonding


- Wash hand thoroughly with soap and water. Clean the working desk area and all related tools with solvent or degreasing agent.
- Use tweezer to take out the strain gage from package and fix it with low tack adhesive tape .
- Position the gage against the layout lines. For very accurate work, a low magnification microscope may be used.



http://www.efunda.com/designstandards/sensors/strain_gages/strain_gage_install_bond.cfm


單秋成

- Apply adhesive according to manufacturer's recommendation. Do not spread the adhesive throughout the surface yet as this accelerates curing.



http://www.efunda.com/designstandards/sensors/strain_gages/strain_gage_install_bond.cfm


單秋成



<http://www.nakka-rocketry.net/articles/Gages.PDF>

單秋成


- Press with finger using considerable pressure for duration specified by the manufacturer.(pressure and temperature from the finger aid curing)
- Special clamping tool and oven curing may be needed for transducer grade operation.



<http://www.kyowa-ei.co.jp/english/images/whats.pdf>

單秋成


Transducer grade preparation often involves clamping with special tool and baking in the oven to ensure thorough curing.



From Krak Gage catalogue

單秋成

Soldering of lead wire



http://www.vishay.com/brands/measurements_group/guide/tt604/604index.htm

單秋成

Cleaning, checking and protection

- Clean the solder flux from the joints.
- Inspect the gage bonding and solder joints.
- Check gage resistance and insulation.
- Anchor the lead wires and connecting wires.
- Apply appropriate protective coating.
- Check bridge wiring and resistance.

單秋成

Examples of Bad installation


- Misaligned gage
- Unbonded backing
- Insufficient curing
- Bumps and wrinkles in the grid
- Trapped gas bubbles
- Uneven adhesive layer
- Bad lead wire soldering
- Insufficient insulation or protection

http://www.vishay.com/brands/measurements_group/guide/ta/iv/iv.htm

單秋成

Examples of Bad installation

➤ Gage Misalignment



Misaligned


Aligned

http://www.vishay.com/brands/measurements_group/guide/ta/iv/iv.htm

單秋成

Examples of Bad installation

➤ Trapped gas bubble



Unacceptable


Bubble-free

http://www.vishay.com/brands/measurements_group/guide/ta/iv/iv.htm

單秋成

Examples of Bad installation

➤ Trapped foreign matter



Unacceptable


Bump-free

http://www.vishay.com/brands/measurements_group/guide/ta/iv/iv.htm


單秋成

Examples of Bad installation


Bad solder joint



Cold Solder Joint




Solder Bridge



Solder Peak

Interfere with flux removal and environmental protection




Residual flux

http://www.vishay.com/brands/measurements_group/guide/ta/iv/iv.htm


單秋成

Examples of Bad installation

➤ Defective protective coating



Unbonded Coating




Coating Void


http://www.vishay.com/brands/measurements_group/guide/ta/iv/iv.htm

單秋成

Examples of Bad installation



Unanchored Cable




Anchored Cable

http://www.vishay.com/brands/measurements_group/guide/ta/iv/iv.htm

單秋成

Examples of Bad installation


- Good lead wire anchoring practice (with bondable terminals)



單秋成

Examples of Bad installation


- Good lead wire anchoring practice (without bondable terminals)



單秋成

Examples of Bad installation

- Lead wire motion leading to tunnel in coating




Tunnel

No Tunnel

http://www.vishay.com/brands/measurements_group/guide/ta/iv/iv.htm

單秋成



http://www.eng.ualgary.ca/PEC/2004/2_PUC_Presentation.PDF

單秋成

Introduction to resistance strain gage


- Equipment for strain measurement.
- Basic theory of resistance strain gage
- Fundamental structure of strain gages
- How to Install a strain gage
- The Wheatstone bridge
- Factors that affect the accuracy of strain gages
- How to select a suitable strain gage

單秋成

The Wheatstone Bridge

單秋成

The Wheatstone bridge




$$e = \left[\frac{R_2}{R_1 + R_2} - \frac{R_3}{R_3 + R_4} \right] E$$

<http://www.ae.gatech.edu/people/jcraig/ae3145/Lab2/strain-gages.pdf>

單秋成

The Wheatstone bridge



$$e = \left[\frac{R_2}{R_1 + R_2} - \frac{R_3}{R_3 + R_4} \right] E$$

$$= \frac{R_2 R_4 - R_1 R_3}{(R_1 + R_2)(R_3 + R_4)} E$$

Bridge balanced if:

$$R_2 R_4 = R_1 R_3$$

Suppose $R_1 = R_4$, $R_2 = R_3$

$$de = \frac{\partial e}{\partial R_1} dR_1 + \frac{\partial e}{\partial R_2} dR_2 + \frac{\partial e}{\partial R_3} dR_3 + \frac{\partial e}{\partial R_4} dR_4$$

<http://www.ae.gatech.edu/people/jcraig/ae3145/Lab2/strain-gages.pdf>

單秋成

The Wheatstone bridge

$$de = \frac{\partial e}{\partial R_1} dR_1 + \frac{\partial e}{\partial R_2} dR_2 + \frac{\partial e}{\partial R_3} dR_3 + \frac{\partial e}{\partial R_4} dR_4$$

or

$$de = \left[\frac{R_1 R_2}{(R_1 + R_2)^2} \left(\frac{dR_1}{R_1} - \frac{dR_2}{R_2} \right) + \frac{R_3 R_4}{(R_3 + R_4)^2} \left(\frac{dR_3}{R_3} - \frac{dR_4}{R_4} \right) \right] E$$

Ignoring second order terms: Non-linearity may occur!!

$$de = \frac{1}{4} \left[\frac{dR_1}{R_1} - \frac{dR_2}{R_2} + \frac{dR_3}{R_3} - \frac{dR_4}{R_4} \right] E$$


Note the signs!

$$de = \frac{GF}{4} [\varepsilon_1 - \varepsilon_2 + \varepsilon_3 - \varepsilon_4] E$$

<http://www.ae.gatech.edu/people/jcraig/ae3145/Lab2/strain-gages.pdf>

單秋成

The Wheatstone bridge




$$de = \frac{1}{4} \left[\frac{dR_1}{R_1} - \frac{dR_2}{R_2} + \frac{dR_3}{R_3} - \frac{dR_4}{R_4} \right] E$$

$$de = \frac{GF}{4} [\varepsilon_1 - \varepsilon_2 + \varepsilon_3 - \varepsilon_4] E$$

<http://www.ae.gatech.edu/people/jcraig/ae3145/Lab2/strain-gages.pdf>


單秋成

How to form a bridge




單秋成

How to form a bridge



單秋成

How to form a bridge




單秋成

Interrogating the Wheatstone Bridge

單秋成

The null indication method



Slow and inefficient!
Not easily automated!

單秋成

Basic Op-Amp circuits


Differential Amplifier

Rule II : $(V_1 - V_-)/R_1 = I_1 = (V_- - V_{out})/R_f$
so: $V_- = (V_1 R_f + V_{out} R_1)/(R_1 + R_f)$

Rule II : $(V_2 - V_+)/R_1 = I_2 = V_+/R_f$
so: $V_+ = V_2 R_f/(R_1 + R_f)$

Since $V_+ = V_-$, can write as


$$V_{out} = (V_2 - V_1) R_f / R_1$$



- Another option for carrying out subtraction.
- Good common mode rejection.

<http://www.ee.unb.ca/Courses/EE3121/AdditionalMaterial/OpAmpsIntro.pdf>


單秋成



Basic Op-Amp circuits

Instrumentation Amplifier

Main aim is to improve the input impedance while maintaining a good common mode rejection



Rule II: no input I, \therefore same I flows thru R_1 - R_2 - R_1

Rule I: $V_A = V_1$, $V_B = V_2$, $\therefore (V_1 - V_2) = IR_2$

Also $(V_3 - V_1) = IR_1$, $(V_2 - V_4) = IR_1$, $\therefore V_4 - V_3 = (V_2 - V_1) - 2(V_1 - V_2) R_1/R_2$

$$V_{out} = R_4/R_3(V_4 - V_3) = \boxed{(V_2 - V_1) (1 + 2R_1/R_2) R_4/R_3}$$

<http://www.ee.unb.ca/Courses/EE3121/AdditionalMaterial/OpAmpsIntro.pdf>

單秋成

3 Op-amp in-amp single chip





Figure 2-17: AD623 single-supply in-amp architecture



http://www.analog.com/library/analogDialogue/archives/39-05/op_amp_applications_handbook.html

單秋成




www.analog.com/library/analogDialogue/archives/39-05/Web_Ch4_final.pdf



單秋成




Bridge balancing



Series R:
Must be very small.
Difficult to apply!




Shunt R:
Usually large.
Easier to apply!




<http://www.ae.gatech.edu/people/jcraig/ae3145/Lab2/strain-gages.pdf>

單秋成

Bridge Calibration



Difficult to apply a
very small resistance
(~0.1Ω) accurately



Easier to apply a
large precision
resistor

$$V = A \frac{GF}{4} [\epsilon_1 - \epsilon_2 + \epsilon_3 - \epsilon_4] E$$

<http://www.ae.gatech.edu/people/jcraig/ae3145/Lab2/strain-gages.pdf>

單秋成

Introduction to resistance strain gage

- Equipment for strain measurement.
- Basic theory of resistance strain gage
- Fundamental structure of strain gages
- How to Install a strain gage
- The Wheatstone bridge
- Factors that affect the accuracy of strain gages
- How to select a suitable strain gage

單秋成

Temperature induced apparent strain

單秋成

Temperature induced apparent strain

Temperature affects:

- Resistivity of a material.
- Thermal expansion of the
 - ✓ gage material
 - ✓ structure to be measured.

Note that the temp. effects vary with temperature

單秋成

Temperature effect

Table 2. Properties of Various Strain Gage Grid Materials

Material	Composition	Use	GF	Resistivity (Ohm/mil-ft)	Temp. Coef. of Resistance (ppm/F)	Temp. Coef. of Expansion (ppm/F)	Max Operating Temp. (F)
Constantan	45% Ni, 55% Cu	Strain Gage	2.0	290	6	8	900
Isoelastic	36% Ni, 8% Cr, 0.5% Mo, 55.5% Fe	Strain gage (dynamic)	3.5	680	260		800
Manganin	84% Cu, 12% Mn, 4% Ni	Strain gage (shock)	0.5	260	6		
Nichrome	80% Ni, 20% Cu	Ther-mometer	2.0	640	220	5	2000
Iridium-Platinum	95% Pt, 5% Ir	Ther-mometer	5.1	135	700	5	2000
Monel	67% Ni, 33% Cu		1.9	240	1100		
Nickel			-12	45	2400	8	
Karma	74% Ni, 20% Cr, 3% Al, 3% Fe	Strain Gage (hi temp)	2.4	800	10		1500

<http://www.ae.gatech.edu/people/jcraig/ae3145/Lab2/strain-gages.pdf>

單秋成

Temperature effect

Table 2. Properties of Various Strain Gage Grid Materials

Material	Composition	Use	GF	Resistivity (Ohm/mil-ft)	Temp. Coef. of Resistance (ppm/F)	Temp. Coef. of Expansion (ppm/F)	Max Operating Temp. (F)
Constantan	45% Ni, 55% Cu	Strain Gage	2.0	290	6	8	900

For a “constantan” gage on an aluminum substrate with a thermal expansion coefficient of 13 ppm/ °F, the differential thermal expansion strain is:

$$\varepsilon = 13 - 8 = 5 \text{ microstrain} / ^\circ F$$

Thus the net apparent strain due to resistive as well as expansion effects would be roughly:

$$\varepsilon = 3 + 5 = 8 \text{ microstrain} / ^\circ F \quad \text{Note: GF=2.0}$$

$$GF = \frac{dR / R}{\varepsilon}$$

<http://www.ae.gatech.edu/people/jcraig/ae3145/Lab2/strain-gages.pdf>

單秋成

Self Temperature compensated gages (STC gages)


The temperature coefficients of the grid materials depend on:

- ✓ Alloying contents.
- ✓ Degree of cold working/heat treatment.

Hence there is a batch to batch difference in temperature coefficient even for the same alloy.

單秋成

Self Temperature compensated gages



http://www.vishay.com/brands/measurements_group/guide/tn/tn513/513b.htm

單秋成

Temperature compensation

- Temperature effect on strain measurement




- ✓ Temperature coefficient of the grid.
- ✓ Thermal expansion mismatch between the gage material and the substrate structure.
- ✓ Lead wire resistance changes.

單秋成

Temperature compensation


➤ Active-dummy method



<http://www.kyowa-ei.co.jp/english/images/whats.pdf>

單秋成

Temperature compensation for lead wire



For remote measurement, the lead wire resistance is considerable and will:


- subject to temperature effects.
- Cause desensitization of signals.

<http://www.ae.gatech.edu/people/jcraig/ae3145/Lab2/strain-gages.pdf>

<http://www.kyowa-ei.co.jp/english/images/whats.pdf>

單秋成

Temperature compensation for lead wire (3 lead wire technique)



單秋成

Other factors that will affect a strain gage

- Large plastic strain
- Corrosive environment
- Cyclic fatigue
- Magnetic field



<http://www.kyowa-ei.co.jp/english/images/whats.pdf>

單秋成

Introduction to resistance strain gage


- Equipment for strain measurement.
- Basic theory of resistance strain gage
- Fundamental structure of strain gages
- How to Install a strain gage
- The Wheatstone bridge
- Factors that affect the accuracy of strain gages
- How to select a suitable strain gage

單秋成

Selecting a gage

單秋成

Different types of strain gages





http://www.vishay.com/brands/measurements_group/strain_gages/mm.htm


單秋成

Different types of strain gages

- Difference in make-up
 - ✓ Backing sheets
 - ✓ Metal foil
 - ✓ cement
- Difference in sizes
- Difference in shapes

單秋成






2 gauge 90 degree rosette


<http://courses.washington.edu/mengr556/Examples%20of%20strain%20gauges.pdf>

單秋成

- For shear and torque measurement



單秋成




Full bridge gages for bending beam.

<http://www.blh.de/wiring.htm>

單秋成

Circular diaphragm gage for pressure transducers




<http://www.blh.de/pdf/g/306p14.pdf>

<http://courses.washington.edu/mengr556/Examples%20of%20strain%20gauges.pdf>

單秋成

Examples of special gauge layouts:

250RA




GAGE LENGTH	OVERALL LENGTH	GRID WIDTH	OVERALL WIDTH
0.250 ES	0.550 CP	0.125 ES	0.847 CP
6.35 ES	13.97 CP	3.18 ES	21.51 CP
Matrix Size		0.78L x 0.93W	
		19.8L x 23.6W	

ES = Each Section
S = Section (S1 = Sec 1)
CP = Complete Pattern
M = Matrix

inches
millimeters

250UY



GAGE LENGTH	OVERALL LENGTH	GRID WIDTH	OVERALL WIDTH
0.250 ES	0.750 CP	0.125 ES	0.750 CP

45 rectangular rosette

60 delta rosette

http://courses.washington.edu/mengr556/Strain_basics.pdf

單秋成

020MT



1X



2X


GAGE LENGTH	OVERALL LENGTH	GRID WIDTH	OVERALL WIDTH
0.020 ES	0.385 CP	0.025 ES	0.100 CP
0.51 ES	9.78 CP	0.64 ES	2.54 CP
Matrix Size		0.48L x 0.19W	
		12.2L x 4.8W	

Strain gradient gauge

http://courses.washington.edu/mengr556/Strain_basics.pdf



單秋成

➤ Weldable strain gage



Measurement Group strain gage catalogue


單秋成

SL x 8.1W		SA-XX-20CBW-120	120 ±0.4%	88.00			
		SK-XX-20CBW-350	350 ±0.4%	93.00			
							
For use on concrete and for strain integration on large specimens.							
OVERALL WIDTH	N2A-XX-40CBY-120	120 ±0.2%	144.00	18.00	9.00		8.00
	N2A-XX-40CBY-350	350 ±0.2%	159.00	18.00	9.00		8.00
0.160	EA-XX-40CBY-120	120 ±0.2%	150.00	18.00	9.00		8.00
	WA-XX-40CBY-120	120 ±0.4%	182.00	*24.00			
4.06	WK-XX-40CBY-350	350 ±0.4%	193.00	*24.00			
	EP-08-40CBY-120	120 ±0.2%	162.00				
.0L x 8.4W	SA-XX-40CBY-120	120 ±0.4%	182.00				
	SK-XX-40CBY-350	350 ±0.4%	193.00				
							

Examples of gauges used for work on concrete. Note the very long gauges used to measure over a representative sample of aggregate and cement.

http://courses.washington.edu/mengr556/Strain_basics.pdf

單秋成




HBWANV-12-250-X-2CB

The complex strain measuring system used for jet engine blade vibrations is now available pre-installed on an easily spot weldable shim for test measurements to 1000°C.

http://www.hitecprod.com/Pdf%20files/70_HtempweldSC.pdf

單秋成




Miniature gage used in printed circuit board

<http://www.kyowa-ei.co.jp/english/kfrs/top.htm>

單秋成


Terminals



<http://www.blh.de/pdf/g/306p19.pdf>

單秋成


Foil gauges are, by the nature of the fabrication process, made in large batches. The characteristics of all gauges in a batch are very consistent. A few gauges in each batch are tested and calibrated and the test values are provided for all gauges in a batch.



http://courses.washington.edu/mengr556/Strain_basics.pdf

單秋成

Data on the temperature dependence of the characteristics of the gauge are also provided. Note that both the resistance and gauge factor vary with temperature.



http://courses.washington.edu/mengr556/Strain_basics.pdf

單秋成

How to choose a gage

B129

單秋成

How to choose a gage

The answer to this question requires the user to define more specifically his application. Namely,

- ✓ What is to be measured?
- ✓ Is this a stress analysis or a transducer application?
- ✓ What are the Ambient Conditions?
- ✓ What is the operating Temperature Range?
- ✓ Is the Magnitude of Strain known?
- ✓ Is the Principal Axis Known?
- ✓ Are there Strain Gradients?
- ✓ What is the duration of the Measurement?
- ✓ Number of cycles
- ✓ Accuracy Requirements

<http://www.blh.de/faq.htm>

單秋成

General selecting procedures

- Determine the gage alloy and backing material.
- Self temperature compensation.
- Gage length and size
- Gage pattern
- Other special requirement (fatigue life, maximum strain, maximum service temperature)





TN-505

單秋成

Strain gage layout for different applications

單秋成

Table 5. Bridge Configurations for Uniaxial Members

K	Configuration	Notes
1		Must use dummy gage in an adjacent arm (2 or 4) to achieve temperature compensation
2		Rejects bending strain but not temperature compensated; must add dummy gages in arms 2 & 4 to compensate for temperature.
$(1+\nu)$		Temperature compensated but sensitive to bending strains
$2(1+\nu)$		Best: compensates for temperature and rejects bending strain.

<http://www.ae.gatech.edu/people/jcraig/ae3145/Lab2/strain-gages.pdf>

單秋成

Table 6. Bridge Configurations for Flexural Members		
K	Configuration	Notes
1		Also responds equally to axial strains; must use dummy gage in an adjacent arm (2 or 4) to achieve temperature compensation
2		Half-bridge; rejects axial strain and is temperature compensated; dummy resistors in arms 3 & 4 can be in strain indicator.
4		Best: Max sensitivity to bending; rejects axial strains; temperature compensated.
2(1+v)		Adequate, but not as good as F-3; compensates for temperature and rejects axial strain.

<http://www.ae.gatech.edu/people/jcraig/ae3145/Lab2/strain-gages.pdf> 單秋成

Table 7. Bridge Configuration for Torsion Members			
No.	K	Configuration	Notes
T-1	2		Half Bridge: Gages at $\pm 45^\circ$ to centerline sense principal strains which are equal & opposite for pure torsion; bending or axial force induces equal strains and is rejected; arms are temperature compensated.
T-2	4		Best: full-bridge version of T-1; rejects axial and bending strain and is temperature compensated.

<http://www.ae.gatech.edu/people/jcraig/ae3145/Lab2/strain-gages.pdf> 單秋成

END

單秋成

Strain gage calibration Lab

準備事項：

- (1) 帶游標卡尺；
- (2) **Review instrumentation amplifier;**
- (3) 複習黏貼應變計方法與注意事項；
- (4) 研習Wheatstone bridge 相關原理，並嘗試回答預習報告中的相關問題；
- (5) 複習梁之彎曲理論，請預先計算一厚度為 t mm，曲率半徑為 R mm之梁，其表面應變為若干。


單秋成

Strain gage calibration Lab

1. Sticking of strain gage.
2. Soldering of lead wire.
3. Bridge completion.
4. Bridge balancing.
5. Direct calibration:- Strip bending.
6. Indirect calibration:- Shunt calibration.
7. Strain gage amplifier characteristics


單秋成

Strain gage calibration Lab




單秋成

Generating a chosen curvature




單秋成

Strain gage calibration Lab



單秋成

Strain gage calibration Lab



單秋成

預習報告

- Suppose R_b and R_s are non-existent, what is the relationship between the Bridge output voltage V , Excitation E and the change in resistance ΔR_g in the active gage.
- What is the gage factor? In the absence of R_b and R_s , what is the relationship between the Bridge output voltage V , Excitation E and the strain ε sensed by the active gage?
- The bridge balance resistors provided are $10\text{ k}\Omega$, *Can they have different values?*

單秋成

預習報告

- What is the use of R_b in the bridge circuit in Figure 1? Please briefly explain the underlying principle.
- What is the use of R_s in the bridge circuit in Figure 1? Please briefly explain the underlying principle.
- Suppose $R_s = 100\text{k}\Omega$ and the bridge is initially balanced. What will the bridge output voltage become if R_s is shunted across the active gage.

單秋成

預習報告

- What happen if +ve and -ve bridge excitation voltage are interchanged?
- What happen if the bridge output and bridge excitations are interchanged (ie. OP+ is interchanged with BS+ and OP- is interchanged with BS-)?
- What is the relation between the surface strain, radius of curvature, Young's modulus and the thickness of a beam under bending?

單秋成

Strain gage amplifier characteristics

- What happen if you interchange the BS+ and BS-?
- What happen if you interchange the OP+ and OP-?
- What happen if you have not zero the bridge before measurement?

單秋成